# AUTOLAND S C I E N T E C H

# How to register your scanner

### Before you begin

You must be registered as a Member in order to register your scanner

 For a detailed guide please review 'How to register as a Member'

#### **1**. Visit us at www.autolandscientechusa.com



## 2. Login to the member's area (top-right of the website)



mber Login	_	_	_	-
Login Passw	ID :			
L	ogin	Forgot passw	vord	
a Our Member You Can Get	Lu Soft	ware Specification		
e Our Member You Can Get	₩ Soft	ware Specification Lastest Technical Info	rmation	
e Our Member You Can Get	→ Soft → The → Free	ware Specification Lastest Technical Info Service - Pack Softw	rmation are Download	
e Our Member You Can Get	<ul> <li>→ Soft</li> <li>→ The</li> <li>→ Free</li> <li>→ ePa</li> </ul>	ware Specification Lastest Technical Info Service - Pack Softw per	rmation are Download	

#### **3.** Click on **iSCAN-II wt Base Unit S/N registration.**

(if you have a VeDis-II, click on the VeDis-II tab on the left side, then click on the VeDis-II Base Unit S/N Registration button)

мемве	R					
LOCATION;	>MEMBER					
		Univers	al Imports(Member)			
Current Date	2014-10-31		Agency	Autoland Scientech USA		
Contact Person	(internet)		ID	\$ common		
Tel	Station and Company		Fax	The second		
Email	and the resident tab.		Company Address	All party in the same little		
		Modify Mem	ber Information Logou	t		
iSCAN-II wt		iSCAN-II wt				
		iSCAN-II wt Software Upgrade		iSCAN-II wt Base Unit S/N Registration		
ISCAN-II ISCAN-II wt Speci		iSCAN-II wt Specific	ation & Changes	iSCAN-II wt Diagnostic cable connection		

### 4. Enter the Unit's serial number (using the format 000xxxx) and press Send.



Image of the serial number can be found on the website

If you see the serial number followed by the word Success you have successfully registered your scanner.



If this fails (with the word Fault), you will need to contact your distributor to correct the situation before you may register and update your scanner.

\*\* If you are still experiencing issues: Take a screenshot of the error message and contact Autoland Scientech USA, Inc. at (512)336-5152